


Pedestal Sign Display

Product Parts

- 1 - Pole
- 1a - Bottom Threaded End
- 2 - Base
- 3 - Frame
- 4 - Graphic Slit



Display Set-Up

Step 1

Remove all parts from box and place on a clean work surface. Screw the Bottom Threaded End (1a) of the Pole (1) into the threaded receptacle in the center of the Base (2).



Step 2

Slide the Frame (3) onto the top of the Pole (1) through the opening on the bottom bracket of the Frame (3). Align the threaded end of the Pole (1) to the threaded receptacle on the bottom of the Frame (3) and turn the frame clockwise to secure.



Step 3

Slide your graphic into the top of the Frame (3) through Graphic Slit (4).



Storage & Care

Place all product parts into shipping box and store in a cool, dry location.
To clean, wipe with damp cloth.